

*BEST COPY*

*AVAILABLE*

*For all of these :*

*THRU OUT FOLDER*

RECEIVING INSPECTION REPORT  
HYCON MFG. COMPANY

No. 11005

RECEIVED FROM Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080003-0

DATE REC'D 1-23-57		P.O. NO.		VENDOR PACKING SLIP NO.	
CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO. 322	DRAWING NUMBER 000000	DWG. DASH OR STANDARD PART NO. 10025	DWG. REV. 0	LOT NO. 0
				CLASS NUMBER 00	OPER. NUMBER 00
				BUY OUT CODE NO. 03	
	DRAWING NO. AND DESCRIPTION			QUANTITY	
				ACCEPTED	REJECTED
25	737458 SHIP MEMO 25234			25	
REMARKS					
<p>RECEIVED BY HMC-1063</p> <p>INSPECTED BY DATE 1/25/57</p> <p>REJECTS RETURNED ON SHIP MEMO NO.</p>					

RECEIVING INSPECTION REPORT  
HYCON MFG. COMPANY

No. 11006

2561 E. COLORADO ST., PASADENA, CALIF.

RECEIVED FROM

DATE REC'D 1-23-57		P.O. NO.		VENDOR PACKING SLIP NO.	
CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO. 322	DRAWING NUMBER 731755	DWG. DASH OR STANDARD PART NO. 10042	DWG. REV. 0	LOT NO. 0
				CLASS NUMBER 00	OPER. NUMBER 00
				BUY OUT CODE NO. 03	
	DRAWING NO. AND DESCRIPTION			QUANTITY	
				ACCEPTED	REJECTED
129	731755 MACH 2 PART 322-000000-10042-0-0-00-00-03			100	29
REMARKS					
<p>RECEIVED BY HMC-1069</p> <p>INSPECTED BY DATE 1/24/57</p> <p>REJECTS RETURNED ON SHIP MEMO NO.</p>					

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080003-0